

Print Server Compatible Tested List

Release Date: 2008/3/28

No.	Company	Printer Model	USB Port	Parallel Port	Windows Vista 32/64	Note
1.	HP	CLJ 1500L	OK	x		
2.	HP	CLJ 1600	OK	x		
3.	HP	CLJ3000dn	OK	x	OK	
4.	HP	CLJ 3500	OK	x		
5.	HP	CLJ 3500N	OK	x		
6.	HP	CLJ 3600	OK	x		
7.	HP	CLJ 3600n	OK	x		
8.	HP	CLJ 3600dn	OK	x		
9.	HP	CLJ 3700	OK	OK		
10.	HP	CLJ 4600	OK	x		
11.	HP	CLJ 5500	x	OK		
12.	HP	CLJ 5500dn	x	OK		
13.	HP	CLJ CP3505	OK	x	OK	
14.	HP	LaserJet 2605	OK	x		
15.	HP	LaserJet 2700	OK	x		
16.	HP	LaserJet 4650	OK	x		
17.	HP	CM1015MFP	OK	x		
18.	HP	CM1017MFP	OK	x		
19.	HP	LaserJet 1012	OK	x		
20.	HP	LaserJet 1015	OK	x		
21.	HP	LaserJet 1022	OK	x	OK	(Note2)
22.	HP	LaserJet 1200	OK	OK		
23.	HP	LaserJet 1220	OK	OK		
24.	HP	LaserJet 1300	OK	OK		
25.	HP	LaserJet 1320	OK	OK		
26.	HP	LaserJet 2300	OK	x		
27.	HP	LaserJet 2300L	OK	OK		

“X” means not compatible

Note1 : For some of Lexmark printers, please close bi-directional and choose “WinPrint” processor and RAW printing protocol.

Note2 :This model needs to close bi-directional function.

Print Server Compatible Tested List

No.	Company	Printer Model	USB Port	Parallel Port	Windows Vista 32/64	Note
28.	HP	LaserJet 2420	OK	OK		
29.	HP	LaserJet 2420dn	OK	OK		
30.	HP	LaserJet 4200L	x	OK		
31.	HP	LaserJet 4350	OK	OK		
32.	HP	LaserJet 5100LE	x	OK		
33.	HP	LaserJet 5100SE	x	OK		
34.	HP	LaserJet 5200L	OK	OK		
35.	HP	LaserJet 3015	OK	OK		
36.	HP	LaserJet 3020	OK	OK	OK	
37.	HP	LaserJet 3030	OK	OK		
38.	HP	LaserJet 3050	OK	x		
39.	HP	LaserJet 3050z	OK	x	x	
40.	HP	LaserJet 3200	OK	x		
41.	HP	LaserJet 3300	OK	OK		
42.	HP	LaserJet 3330mfp	OK	OK		
43.	HP	LaserJet 3380	OK	OK		
44.	HP	LaserJet M1005MFP	OK	x	OK	
45.	HP	LaserJet P2015	OK	x	OK	
46.	HP	Deskjet 450	OK	x		
47.	HP	Deskjet 810C	OK	OK		
48.	HP	DeskJet 845C	OK	x	OK	
49.	HP	Deskjet 880C	OK	OK		
50.	HP	Deskjet 882C	OK	OK		
51.	HP	Deskjet 895cxi	OK	OK	OK	
52.	HP	Deskjet 920C	OK	OK		
53.	HP	Deskjet 960	OK	x		

“X” means not compatible

Note1 : For some of Lexmark printers, please close bi-directional and choose “WinPrint” processor and RAW printing protocol.

Note2 :This model needs to close bi-directional function.

Print Server Compatible Tested List

No.	Company	Printer Model	USB Port	Parallel Port	Windows Vista 32/64	Note
54.	HP	Deskjet 970cxi	OK	OK	OK	
55.	HP	Deskjet 980	OK	x		
56.	HP	Deskjet 990	OK	x		
57.	HP	Deskjet 1120C	OK	x		
58.	HP	Deskjet 1125C	x	OK		
59.	HP	Deskjet 1180C	OK	OK		
60.	HP	Deskjet 3325	OK	x		
61.	HP	Deskjet 3535	OK	x		
62.	HP	Deskjet 3550	OK	x		
63.	HP	Deskjet 3650	OK	x		
64.	HP	Deskjet 3820	OK	OK		
65.	HP	Deskjet 5160	OK	x		
66.	HP	Deskjet 5550	OK	x		
67.	HP	DeskJet 5652	OK	OK		
68.	HP	DeskJet 5740	OK	x		
69.	HP	Deskjet 6122	OK	OK		
70.	HP	DeskJet 6540	OK	x		
71.	HP	DeskJet 6840	OK	x		
72.	HP	DeskJet845C	OK	x	OK	
73.	HP	Deskjet 9300	OK	OK		
74.	HP	Deskjet 9650	OK	OK		
75.	HP	Deskjet D2360	OK	x		
76.	HP	Deskjet D4260	OK	x	OK	
77.	HP	Deskjet F2180	OK	x	OK	
78.	HP	Deskjet F380	OK	x	OK	
79.	HP	Business 1000	OK	x		
80.	HP	Business 1100d	OK	OK		

“X” means not compatible

Note1 : For some of Lexmark printers, please close bi-directional and choose “WinPrint” processor and RAW printing protocol.

Note2 :This model needs to close bi-directional function.

Print Server Compatible Tested List

No.	Company	Printer Model	USB Port	Parallel Port	Windows Vista 32/64	Note
81.	HP	Business 1200d	OK	OK		
82.	HP	OfficeJet J5780	OK	x	OK	
83.	HP	OfficeJet Pro K5300	OK	x		
84.	HP	OfficeJet Pro K5400	OK	x		
85.	HP	OfficeJet Pro K5400dn	OK	x	OK	
86.	HP	OfficeJet Pro K850	OK	OK		
87.	HP	OfficeJet Pro K850dtn	OK	OK		
88.	HP	OfficeJet Pro L7380	OK	x	OK	
89.	HP	OfficeJet Pro L7580	Ok	x	OK	
90.	HP	OfficeJet 4110	OK	x		
91.	HP	OfficeJet 4255	OK	x	OK	
92.	HP	OfficeJet 5110	OK	OK		
93.	HP	OfficeJet 5510	OK	x		
94.	HP	OfficeJet 5610	OK	x	OK	
95.	HP	OfficeJet 6110	OK	x		
96.	HP	OfficeJet 6210	OK	x		
97.	HP	OfficeJet 6310	OK	x	OK	
98.	HP	OfficeJet 7210	OK	x		
99.	HP	OfficeJet 7410	OK	x	OK	
100.	HP	OfficeJet 9100	OK	x		
101.	HP	OfficeJet 9110	OK	OK		
102.	HP	OfficeJet 9120	OK	OK		
103.	HP	OfficeJet 9130	OK	OK		
104.	HP	OfficeJet V40	OK	x		
105.	HP	Photosmart 145	OK	x		
106.	HP	Photosmart 245	OK	x		
107.	HP	Photosmart 325	OK	x		

“X” means not compatible

Note1 : For some of Lexmark printers, please close bi-directional and choose “WinPrint” processor and RAW printing protocol.

Note2 :This model needs to close bi-directional function.

Print Server Compatible Tested List

No.	Company	Printer Model	USB Port	Parallel Port	Windows Vista 32/64	Note
108.	HP	Photosmart 375	OK	x		
109.	HP	Photosmart 2575	OK	x	OK	
110.	HP	Photosmart 2610	OK	x	OK	
111.	HP	Photosmart 2710	OK	x		
112.	HP	Photosmart 3110	OK	x		
113.	HP	Photosmart 3310	OK	x		
114.	HP	Photosmart 7260	OK	x		
115.	HP	Photosmart 7550	OK	x		
116.	HP	Photosmart 7660	OK	x		
117.	HP	Photosmart 7760	OK	x		
118.	HP	Photosmart 7960	OK	x		
119.	HP	Photosmart 8450	OK	x		
120.	HP	Photosmart 8750	OK	x		
121.	HP	Photosmart A526	OK	x	OK	
122.	HP	Photosmart C3180	OK	x	OK	
123.	HP	Photosmart C4180	OK	x		
124.	HP	Photosmart C4280	OK	x	OK	
125.	HP	Photosmart C6280	OK	x	Ok	
126.	HP	Photosmart C7180	Ok	x	OK	
127.	HP	Photosmart C7280	OK	x	OK	
128.	HP	Photosmart D5160	OK	x	OK	
129.	HP	Photosmart D7160	OK	x		

“X” means not compatible

Note1 : For some of Lexmark printers, please close bi-directional and choose “WinPrint” processor and RAW printing protocol.

Note2 :This model needs to close bi-directional function.

Print Server Compatible Tested List

No.	Company	Printer Model	USB Port	Parallel Port	Windows Vista 32/64	Note
130.	HP	Photosmart D7360	OK	x	OK	
131.	HP	PSC 750	OK	x		
132.	HP	PSC 1110	OK	x		
133.	HP	PSC 1210	OK	x	OK	
134.	HP	PSC 1315	OK	x	OK	
135.	HP	PSC 1350	OK	x		
136.	HP	PSC 1410	OK	x	OK	
137.	HP	PSC 1510	OK	x	OK	
138.	HP	PSC 1610	OK	x	OK	
139.	HP	PSC 2110	OK	x		
140.	HP	PSC 2210	OK	x		
141.	HP	PSC 2310	OK	x		
142.	HP	PSC 2355	OK	x	OK	
143.	HP	PSC 2410	OK	x		
144.	HP	PSC 2510	OK	x		
145.	HP	PSC 4110	OK	x		
146.	Canon	iC D380	OK	x		
147.	Canon	S200SPx	OK	x		
148.	Canon	C350	OK	x		
149.	Canon	i255	OK	x		
150.	Canon	i320	OK	x		
151.	Canon	i355	OK	x		
152.	Canon	i450	OK	x		
153.	Canon	i455	OK	x		
154.	Canon	i6100	OK	OK		
155.	Canon	i6500	OK	OK		
156.	Canon	i9100	OK	x		
157.	Canon	i9950D	OK	x		

“X” means not compatible

Note1 : For some of Lexmark printers, please close bi-directional and choose “WinPrint” processor and RAW printing protocol.

Note2 :This model needs to close bi-directional function.

Print Server Compatible Tested List

No.	Company	Printer Model	USB Port	Parallel Port	Windows Vista 32/64	Note
158	Canon	i475D	OK	x		
159	Canon	i560	OK	OK		
160	Canon	i865	OK	OK		
161	Canon	i905D	OK	x	OK	
162	Canon	iR 2010	OK	OK		
163	Canon	iR 6000	x	OK		
164	Canon	iR 8500	x	OK		
165	Canon	iP1000	OK	x		
166	Canon	iP1880	OK	x	OK	
167	Canon	iP1500	OK	x		
168	Canon	iP2000	OK	x		
169	Canon	iP3000	OK	x		
170	Canon	iP3300	OK	x	OK	
171	Canon	iP3500	OK	x	OK	
172	Canon	iP4000	OK	OK		
173	Canon	iP4200	OK	x	OK	
174	Canon	iP4300	OK	x	OK	
175	Canon	iP4500	OK	x	OK	
176	Canon	iP5000	OK	x		
177	Canon	iP6000D	OK	x		
178	Canon	iP8500D	OK	x		
179	Canon	Pro 9000	OK	x		
180	Canon	iX4000	OK	x	OK	
181	Canon	iX5000	OK	x		
182	Canon	PIXMA MP110	OK	x		
183	Canon	PIXMA MP130	OK	x	OK	
184	Canon	PIXMA MP150	OK	x		

“X” means not compatible

Note1 : For some of Lexmark printers, please close bi-directional and choose “WinPrint” processor and RAW printing protocol.

Note2 :This model needs to close bi-directional function.

Print Server Compatible Tested List

No.	Company	Printer Model	USB Port	Parallel Port	Windows Vista 32/64	Note
185.	Canon	PIXMA MP160	OK	x		
186.	Canon	PIXMA MP170	OK	x		
187.	Canon	PIXMA MP180	OK	x		
188.	Canon	PIXMA MP450	OK	x	OK	
189.	Canon	PIXMA MP510	OK	x		
190.	Canon	PIXMA MP700	OK	x		
191.	Canon	PIXMA MP730	OK	x		
192.	Canon	Pro9000	OK	x	OK	
193.	SAMSUNG	ML-1520LP	OK	x		
194.	SAMSUNG	ML-1740	OK	OK		
195.	SAMSUNG	ML-2010	OK	x		
196.	SAMSUNG	SCX-4100	OK	OK		
197.	SAMSUNG	SCX-4200	OK	OK		
198.	SAMSUNG	SCX-4521F	OK	OK	OK	
199.	SAMSUNG	SCX-4720F	OK	OK		
200.	SAMSUNG	SF-565P	OK	OK	OK	
201.	Lexmark	X6170	OK	x	Vista 64 only	
202.	Lexmark	Z603	OK	x		(Note1)
203.	Lexmark	Z615	OK	x		(Note1)
204.	Lexmark	Z705	OK	x		(Note1)
205.	Lexmark	Z810	OK	x		(Note1)
206.	Lexmark	Z816	OK	x		(Note1)
207.	Lexmark	Z818	OK	x	Vista 32 only	(Note1)
208.	Lexmark	E230	OK	OK		
209.	Lexmark	C510	OK	OK		

“X” means not compatible

Note1 : For some of Lexmark printers, please close bi-directional and choose “WinPrint” processor and RAW printing protocol.

Note2 :This model needs to close bi-directional function.

Print Server Compatible Tested List

No.	Company	Printer Model	USB Port	Parallel Port	Windows Vista 32/64	Note
210.	Epson	Aculaser C1900	OK	OK		
211.	Epson	Aculaser C4000	OK	OK		
212.	Epson	Aculaser C4100	OK	OK		
213.	Epson	Aculaser C8600	OK	OK		
214.	Epson	DLQ-3500C	OK	OK		
215.	Epson	EPL-5900L	OK	OK	Vista32 only	(Note2)
216.	Epson	EPL-6100	OK	OK		
217.	Epson	EPL-6200	OK	OK	Vista32 only	
218.	Epson	EPL-N2500	OK	OK		
219.	Epson	EPL-N2750	x	OK		
220.	Epson	EPL-N3000	OK	OK		
221.	Epson	LQ-300+	x	OK		
222.	Epson	LQ-300+II	OK	x	Vista32 only	
223.	Epson	LQ-680C	x	OK		
224.	Epson	LQ-2080C	x	OK		
225.	Epson	Stylus C43UX	OK	x		
226.	EPSON	Stylus C45	OK	x	OK	
227.	Epson	Stylus C63	OK	x		
228.	Epson	Stylus C83	OK	x		
229.	Epson	Stylus C4100	OK	x	OK	
230.	Epson	Stylus COLOR 740	OK	OK	OK	
231.	Epson	Stylus COLOR 880	OK	—		
232.	Epson	Stylus COLOR 1160	OK	x		
233.	Epson	Stylus CX1500	OK	x		
234.	Epson	Stylus CX3100	OK	x		

“X” means not compatible

Note1 : For some of Lexmark printers, please close bi-directional and choose “WinPrint” processor and RAW printing protocol.

Note2 :This model needs to close bi-directional function.

Print Server Compatible Tested List

No.	Company	Printer Model	USB Port	Parallel Port	Windows Vista 32/64	Note
235.	Epson	Stylus CX3700	OK	x		
236.	Epson	Stylus CX3900	OK	x	OK	
237.	Epson	Stylus CX4700	OK	x	OK	
238.	Epson	Stylus CX5100	OK	x		
239.	Epson	Stylus CX5300	OK	x		
240.	Epson	Stylus CX5500	OK	x	OK	
241.	Epson	Stylus CX5900	OK	x	OK	
242.	Epson	Stylus PHOTO 830U	OK	x		
243.	Epson	Stylus PHOTO 935	OK	x		
244.	Epson	Stylus PHOTO 1390	OK	x	OK	
245.	Epson	Stylus PHOTO 2100	OK	OK		
246.	Epson	Stylus PHOTO R210	OK	x		
247.	Epson	Stylus PHOTO R230	OK	x		
248.	Epson	Stylus PHOTO R310	OK	x	OK	
249.	Epson	Stylus PHOTO RX430	OK	x		
250.	Epson	Stylus PHOTO RX510	OK	x		
251.	Epson	Stylus PHOTO RX530	OK	x	OK	
252.	Epson	Stylus PHOTO RX590	OK	x	OK	
253.	Epson	Stylus PHOTO RX630	OK	x		

“X” means not compatible

Note1 : For some of Lexmark printers, please close bi-directional and choose “WinPrint” processor and RAW printing protocol.

Note2 :This model needs to close bi-directional function.

Print Server Compatible Tested List

No.	Company	Printer Model	USB Port	Parallel Port	Windows Vista 32/64	Note
254.	Epson	Stylus PHOTO RX650	OK	x	OK	
255.	Brother	HL-2070	OK	x		
256.	Brother	HL-5240	OK	x		
257.	Brother	MFC-210C	OK	x		
258.	Brother	MFC-215C	OK	x		
259.	Brother	MFC-2820	OK	x		
260.	Brother	MFC-3240C	OK	x		
261.	Brother	MFC-420CN	OK	x		
262.	Brother	MFC-425CN	OK	x		
263.	Brother	MFC-4800J	OK	x		
264.	Brother	MFC-7420	OK	x		
265.	Brother	MFC-7820N	OK	x		
266.	Brother	MFC-8840D	OK	x		
267.	Konica Minolta	Magicolor 2480MF	OK	x	Vista 32 only	(Note2)
268.	Konica Minolta	Magicolor 5550	OK	x		
269.	Konica Minolta	Magicolor 5570	OK	x		
270.	Dell	944	OK	x		
271.	Dell	Mono LaserMFP1125	OK	x		(Note2) No Win2000

“X” means not compatible

Note1 : For some of Lexmark printers, please close bi-directional and choose “WinPrint” processor and RAW printing protocol.

Note2 :This model needs to close bi-directional function.